

**IN THE CLAIMS:**

Please cancel claim 1 without prejudice to or disclaimer of the subject matter recited therein.

Please add new claims 2-7 as follows:

**LISTING OF CURRENT CLAIMS**

Claim 1. (Canceled)

Claim 2. (New) An outdoor water tight lamp comprising:

- a) an upper cap having an upper cap sealing rim having:
  - i) an exterior sloped surface protruding outwardly from an outer periphery thereof;
  - 5 ii) an upper cap joint surface located around an inner periphery thereof; and
  - iii) a convex portion located between the exterior sloped surface and the upper cap joint surface;
- 10 b) a lower cap having a lower cap sealing rim having a lower cap joint surface located around an inner periphery thereof and engaging the upper cap joint surface and creating a water tight seal there between; and
- c) a lamp base connected to the upper cap and the lower cap and located there between.

Claim 3. (New) The outdoor water tight lamp according to claim 2, wherein the lamp base is connected to the upper cap and the lower cap by a plurality of screws, a plurality of nuts, and at least one seal.

Claim 4. (New) The outdoor water tight lamp according to claim 2, wherein the upper cap joint surface is a multi-step structure.

Claim 5. (New) The outdoor water tight lamp according to claim 2, wherein the lower cap joint surface is a multi-step structure.

Claim 6. (New) The outdoor water tight lamp according to claim 2, wherein the upper cap has an upper cap screw bolt hole in a center thereof, the lower cap has an lower cap screw bolt hole in a center thereof.

Claim 7. (New) The outdoor water tight lamp according to claim 6, wherein the lamp base is connected to the upper cap screw bolt hole and the lower cap screw bolt hole by a plurality of screws, a plurality of nuts, and at least one seal.